




FIG. 2



1b →








FIG. 6




FIG. 7




FIG. 8






FIG. 9




FIG. 10





FIG. 11







FIG. 13






FIG. 14







FIG. 16





[illegible]






FIG. 19

FIG. 20




FIG. 21





FIG. 22






FIG. 24







FIG. 25






FIG. 27




FIG. 28




FIG. 29





FIG. 30







FIG. 31


FIG. 32





Angle of Slanted Swash Plates 57 and 85

FIG. 33



Angle of Slanted Swash Plates 57 and 85

FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39





FIG. 40








FIG. 42




FIG. 43







FIG. 44









FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53






FIG. 54




FIG. 55




FIG. 56

